

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1083	carver near press	USPAT	OR	OFF	2006/04/15 12:44
L2	193819	(frame or base or support or tie adj arm) and (adjust\$4 near arm or column or post or bolt or screw) and (tension\$4 near arm or screw or nut or fasten\$4 or connector) and (plate or platen) and press	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 12:44
L3	7755	2 and (press).ti.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 12:48
L4	8100	((228/44.3,4.1,212,213,44.5,44.7,47.1,49.1,49.3,49.4,49.5,49.6) or (100/144,214,295,269.17)).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/04/15 12:52
L5	828613	(frame or base or support or tie adj arm) and (adjust\$4 near arm or column or post or bolt or screw) and (tension\$4 near arm or screw or nut or fasten\$4 or connector) and (plate or platen)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:03
L6	835303	4 or 5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 12:57
L7	828613	6 and (frame or base or support or tie adj arm) and (adjust\$4 near arm or column or post or bolt or screw) and (tension\$4 near arm or screw or nut or fasten\$4 or connector) and (plate or platen)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:05
L8	648289	7 and (load or force or press or press\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:04

EAST Search History

L9	21148	8 and (heat or thermal or thermal\$4) near (expand\$4 or expans\$4 or coeff or coefficient)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:05
L10	1410	4 and 5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:01
L11	1410	10 and (frame or base or support or tie adj arm) and (adjust\$4 near arm or column or post or bolt or screw) and (tension\$4 near arm or screw or nut or fasten\$4 or connector) and (plate or platen)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:02
L12	1299	11 and (load or force or press or press\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:02
L13	1	12 and (tie adj arm)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:03
L14	330	6 and (tie adj arm)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:04
L15	312	14 and (frame or base or support)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:04
L16	271	15 and (load or force or press or press\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:04

EAST Search History

L17	4	16 and (heat or thermal or thermal\$4) near (expand\$4 or expans\$4 or coeff or coefficient)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:05
L18	4	16 and (adjust\$4 near arm or column or post or bolt or screw) and (tension\$4 near arm) and (plate or platen)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/15 13:06